

2023: Port of Arendal

Eydehavn main quay: A slipp of rocks observed under Main quay Eydehavn (red triangle)

By immediate effect until further notice

- Reduction in max vessel draft alongside to **8 mtrs** from bollard no 6 (86 m) until quay end in SW
(Verified minimum depth in damage area (**blue area**/ **rock observed**: 9 mtrs):
- No crane operation/ loading/unloading between bollard no 4 and no 6. Area is physical cordoned off

Pile no 14 affected by the slipp. All other piles verified intact

All bollards/fenders/ intact and verified for securing vessels alongside

